



3941 Courtland Terrace
Rockford, IL. 61109
815-986-6705 or 815-519-5673

SIGNS ♦ BANNERS ♦ POSTERS ♦ DECALS
MAGNETIC SIGNS ♦ VEHICLE GRAPHICS/WRAPPS ♦ DISPLAYS

Congratulations

on your purchase of your flexible magnetic signs. All Hugeprints products are precision-made to meet your needs and specifications, while retaining their durability and appearance for years. Proper use and care will help to extend the life of your magnet and protect the metallic surface to which it is applied.

Important — General Caution

Applying any material to a painted metallic surface without Following All Instructions For The Use And Care may result in damage to that surface. Hugeprints takes pride in keeping its product users apprised of information that helps prevent such consequences. By following these instructions, you can ensure top performance. Failure to follow these instructions and tips may cause damage to the magnetic material and/or surface to which applied. Hugeprints will not be held liable for any damage caused by abuse, misuse, or failure to follow the "Use, Care and Cleaning instructions".

Use, Care and Cleaning of Your Flexible Magnet

Storing Flexible Magnet

1. When not using flexible magnetic sheet, keep it in a clean, dry place.
2. Stack flat magnet on a level surface. Avoid placing objects (such as cartons) on top that could damage the face; do not stack with magnetic sides facing each other.

Preparing Magnetic-Receptive Surfaces

1. Before affixing magnetic sheet to a metal surface, be sure all surface paints, clear coats and waxes are cured (hardened).*
2. Clean the metallic surface and the magnet with mild detergent.
3. Wipe with a soft cloth or allow to dry.

*(Approximate curing times: paint—90 days; clear coat—60 days; wax—2 days.)

Applying Flexible Magnet

1. If possible, affix to smooth, flat or gently curved metallic surfaces.
2. Make sure the entire magnet is flat against the metal surface (i.e., no air pockets).
3. If you place the magnet in the wrong position, completely remove the magnet from the surface and reaffix. Do not pull the magnet across the surface, or it may stretch due to the resistance caused by the high magnetic strength.
4. Avoid use on horizontal metal surfaces exposed to direct sunlight (such as automobile hoods), temperatures exceeding 1600 F (710 C) or temperatures below -15° F (-26° C). Exposure to cold weather will make the magnet more brittle so use caution when handling.
5. Be aware that long-term use on surfaces frequently exposed to sunlight (such as vehicles) can result in uneven fading of the surface because the magnet-covered area is shielded from ultraviolet rays.
6. Avoid use on non-metallic body fillers, simulated wood grain siding and repainted surfaces.

Cleaning Flexible Magnet

1. To guard against moisture and dirt buildup between the magnet and the metal surface (particularly on outdoor applications), remove the magnet at regular intervals. Clean both the magnet and metal surface with mild detergent; wipe with a soft cloth or allow to air-dry. (For vehicle-mounted signs, remove and clean DAILY.)
2. After waxing and polishing, allow 2 days for wax to cure before applying magnets.